

August 7, 1961

*File: East Fork
Virgin R.*

Glendale Irrigation Company
c/o Mr. Charles C. Anderson, Pres.
Glendale, Utah

Gentlemen:

This will acknowledge your letter of July 20, 1961 in which you demanded we check the Parshall flumes in the Mt. Carmel, Orderville, and Glendale Irrigation Company canals.

Please be advised that these devices always measure water correctly as long as they are properly installed, maintained and read. The maintenance and installation of these devices are the responsibility of the water users of the canals mentioned. We do not question their accuracy. If you feel they are not properly measuring the water then we suggest that you obtain the services of a competent engineer and have them make whatever checks you may wish.

Yours very truly,

Donald C. Horneth
DISTRIBUTION ENGINEER

DCN/wh

CC: Mr. Earl Staker
P. O. Box 347
Cedar City, Utah

Mr. Charles F. Hepworth
Orderville, Utah

Glendale, Utah

July 20, 1961

Utah State Engineer


Mr. Wayne D. Criddle

Salt Lake City, Utah

Dear Sir:

In the last meeting of the Glendale Irrigation Co. Board of Directors it was felt that the measuring devices in the ditches of the Mt. Carmel, Orderville and Glendale Irrigation Companies, are not measuring the water right. We want you to take steps immediately to have the same checked for accuracy.

Sincerely,


Willard Mackelprang, President



W.D.C.
PC 91